


8-11

ZQ-6057-V-4

Figure 8-6 TEST NO. 2 – PRE TEST COLLISION CONFIGURATION



8-12

ZQ-6057-V-4

Figure 8-7 TEST NO. 2 – POST TEST COLLISION SCENE






8-13

ZQ-6057-V-4

Figure 8-8 TEST NO. 2 – PRE AND POST EXTERIOR VIEWS, CAR NO. 1 - CHEVELLE





8-14

ZQ-6057-V-4

Figure 8-9 TEST NO. 2 – PRE AND POST EXTERIOR VIEWS, CAR NO. 2 - PINTO






8-15

ZQ-6057-V-4

Figure 8-10 TEST NO. 2 – PRE AND POST INTERIOR VIEWS, CAR NO. 1 - CHEVELLE

8-16



ZQ-6057-V-4





Figure 8-11 TEST NO. 2 – POST INTERIOR VIEW, CAR NO. 2 - PINTO